

PEA Committee on Worksite Safety & Health Report

"Safety First"

Joseph J. Mazur, Jr. Chairperson.

January 27, 2010

<u>P.E.A.</u> <u>file #</u>	<u>Worksite</u>	<u>Problem</u>	<u>Description</u>	<u>Date Filed</u>	<u>PEOSH</u> <u>Filed</u>	<u>Status</u>
05-105	PS # 5	Water Damage	Roof leaks causing water damage to walls and ceilings.	11/4/2005	9/22/2006	OPEN
05-107	PS # 5	Water Damage	Roof leaks causing water damage to walls and ceilings.	11/4/2005	9/22/2006	OPEN
07-101	PS # 5	Water damage	Roof leaks are causing falling paint & plaster -2nd fl. rooms.	12/17/2007	No	OPEN
07-102	PS # 5	Security Cameras	Security cameras not functioning on the outside of the bldg.	10/17/2007	No	OPEN
07-107	PS # 5	Water damage	Water infiltration causing falling paint/plaster - gym ceiling.	12/14/2007	No	OPEN
07-108	PS # 5	Water damage	Water infiltration causing falling paint/plaster - back stairwell.	12/14/2008	No	OPEN
07-118	PS # 5	Keys	Many staff do not have keys to their doors.	4/25/2008	No	OPEN
07-119	PS # 5	Water damage	Water leaked into Room 223. Stained tiles.	4/23/2008	4/25/2008	OPEN
08-106	PS # 10	Water Infiltration	Water infiltration causing mold throughout building.	10/28/2008	12/17/2008	OPEN
08-111	PS # 5	Accident Invest.	Staff member slipped on stairs fracturing his ankle.	N/A	3/4/2009	OPEN
08-115	PS # 12	Stairs	Stairs are in poor condition; chipped treads, improper handrails.	2/11/2009	3/9/2009	OPEN

08-117	PS # 7	Water Infiltration	Roof in auditorium leaks. Water damage throughout area.	05/12/2009	-	OPEN
09-101	PANTHER	IAQ	Rooms/hallways are hot. HVAC not functioning properly	09/15/2009	-	OPEN
09-102	District	IAQ	Sodexo not supplying and changing HVAC filters as per IAQ prgm	N/A	9/24/2009	OPEN
09-103	PS #12	Fluoresc. Ballasts	Many fluorescent ballasts are out in rooms.	10/22/2009	-	OPEN
09-104	PS # 5	Heat	Basement room has no heat since space heaters were removed.		-	OPEN
09-105	Int'l HS	Bathrooms	Bathrooms are in unsanitary condition due to poor cleaning.	11/12/2009	-	OPEN
09-106	JFK	HVAC	Univent in rm 206 has most major parts removed for past 2 yrs.	11/16/2009	-	OPEN
09-108	GFA/16	IAQ	Several staff members are experiencing breathing problems.	12/01/2009	-	OPEN

The entire January 2010 WSH Report can be found at [www. PatersonEA.org](http://www.PatersonEA.org) on the Faculty Room page.



“Safety First”

This report was completed on January 20, 2010 and contains all information provided to this Committee by the worksite as of this date.

An “E” after the file number designates that the complaint was filed through e-mail to the District. No written complaint form was sent. Should the problem continue, and a written complaint sent to the District, or a PEOSH complaint filed, the “E” designation will be dropped.

The following complaints need updating by the worksites. Please respond in writing as to the status of the complaint and if the problem still exists:

**09-102 PANTHER HVAC
(Second Request)**

IF SCHOOLS FAIL TO RESPOND AND INFORM THIS COMMITTEE, OPEN COMPLAINTS WILL BE DESIGNATED AS “CLOSED” AFTER TWO (2) REQUESTS FOR INFORMATION.

Any errors which are discovered in the content of this report should be made in writing to :

Paterson Education Association

Committee on Worksite Safety & Health

445 Straight Street

Paterson, New Jersey 07501-2935

or to: JMazur@Paterson.k12.nj.us